



Radio Building Beginning



Radio Building Demo



3rd Floor Exposed




Tower being Exposed
Hidden Stone



Tower being Exposed



3rd Floor Windows



Hidden Carved Stone on
1st floor



Hidden Pilaster Capitals discovered



Hidden Pilaster Capitals discovered



Hammer Damage on all Capitals. This is the best one





Original Cornice profile discovered



Brick Restoration is extensive



Brick Restoration is extensive



Brick Restoration is extensive



Brick Restoration is extensive



Oak 2nd Floor window head and
carved Rope Detail



Hidden Mullions Found



Hidden Mullions Found



Hidden Mullions Found



Hidden Mullions Found



Hidden Mullions Found




Hidden Mullion brought to shop for restoration effort



Hidden Mullion brought to shop for restoration effort



Hidden Mullion brought to shop for restoration effort




Mullions are one story in height




This may be a photo of the original Mullions and windows



The Union Block at the corner of Higgins and Main, 1900. The corner building housed the Western Montana National Bank until it moved to the new Montana Block Building on the next corner in 1910. The large building to the east, is now the Radio Central Building. The Chicago Bee Hive store occupied the other corner which is now the site of the Darkroom. UTM 86-62



This could be the Union Block
Front Facade



Pilaster Capital top visible over
Parapet



Architectural Pilaster Capital



Tower Roof and Capitals Installed



Capitals Installed



Capitals Installed. Waiting for Cornice
Trim